


self-made tool auto-checking operating

Tool setting method 1 (parameter No. 68 = 1)



◆ Ready to work

- ◆ system is in 【free】 state
- ◆ The main interface switch to 【main page】

◆ Instructions

1. Open the tool setting function, parameter 68 is set to 1, mode 1;
2. Set the effective level of the knife counterparts, the default normally open, the relevant parameters No. 70;
3. Set tool presetter mode, parameter No. 71, 1: fixed tool presetting tool 0: floating tool setter;
4. Set the initial scan position of the tool presetter, as shown in Figure 2 above, the relevant parameters for the 72,73,74 number;
(If the 71 parameter is 0, ignore this step);
5. The first time the knife (measuring knife position);
6. Move the tool Z to the workpiece surface (Z program zero point) as shown above ① and clear Z workpiece coordinate;

7. Click the button [2nd] and [A-] to execute the current tool setter position measurement in sequence. The operation flow is as shown in the above figure, and ① moves ② position (the position set in step 4), and then ③ searches for the tool setting movement until it stops. (Execute probe.nc) (If parameter 71 is 0, you need to manually move the tool to the tool presetter, and then perform the tool setting operation)

8. The current tool alignment tool position measurement is completed;
9. If you do not change the workpiece zero conditions, the replacement of different length of the tool, you only need to repeat in any position Step 7 action, you can automatically complete the knife on the knife action;
10. If the Z zero position changes need to repeat 6-9 steps can be;

◆ note

- ◆ Step 4 of the knife on the scanner position parameters set for the mechanical coordinate position;
- ◆ Step 6 Z Workpiece zero calibration and step 7 Initial tooling must be performed with the same tool; the tool can not be re-installed;
- ◆ If the zero point of the Z-axis workpiece changes, you need to re-measure the knife position measurement;

Tool setting method 2 (parameter No. 68 = 2)

Custom features, temporarily do not use!

The principle of self-made tool auto-checking and macro program analysis

Tool setting method 1 (parameter No. 68 = 1)




Chart Description:

A and C: Zero point offset of G53 coordinate system (relative amount of G53 zero point to mechanical zero point);

B and D: G54 workpiece coordinate system zero offset (G54 workpiece zero to G53 zero relative amount)

T1, T2, T3: indicates the coordinate system under different tool lengths

1: After executing the reset operation, B and D are determined.

2: After the tool length is changed, the alignment of A and C will be caused after executing the tool alignment.

3: A and C changes will cause the G54 coordinate system to change the absolute position of the workpiece;

$$Z \text{ Absolute position (G54)} = Z \text{ Mechanical position (MAH)} - A (C) - B (D) ;$$

Macro (probe.nc) analysis

- Related Macro Address Description:

#0- #49 for each subroutine internal private variables;

#50- #499 is the system internal variable area 1;

#500- #999 is the system parameter area;

#1000- #1999 is the system internal variable area 2;

400: G53 coordinate system Z zero point offset after execution of the tool presetting

402: same as # 400;

403: Coordinate system enable switch is automatically corrected after tool execution

404: Tool nose point at the G53 Z coordinate of the tool presetter (record the Z position of

the initial tool setting)

#571:71- Initial tool's position;

#572:72--Initial probe position on X axis(MAC POS);

#573:73--Initial probe position on Y axis(MAC POS);

#574:74--Initial probe position on Z axis(MAC POS);

#575:75--back distance after probe;

#578:78- Z axis lifting protection speed

864: X-axis machine position;

865: Y-axis machine position;

866: Z axis mechanical position;

870: Z axis G53 coordinate position

- probe.nc Macro analysis

```
G04P0;          ----- Pause 0s, read the current machine coordinate position correctly
                  for the subsequent program
M5;             ----- Close the spindle
# 20 = # 864    ----- Read the current X machine coordinate position
# 21 = # 865    ----- Read the current Y machine coordinate position
# 22 = # 866    ----- Read the current Z machine coordinate position
IF # 571EQ0GOTO1; ----- Floating tool presetter or fixed tool selection
(Fixed tool presetter mode, find the knife position XYZ need to feed)
# 1 = # 572- # 20
# 2 = # 573- # 21
# 3 = # 574- # 22
GOTO2
N1 # 1 = 0
# 2 = 0
# 3 = 0
N2G91G00Z # 3    ----- Move the machine tool to the tool presetter Z position
G91G00X # 1Y # 2 ----- Move the machine to the tool setting XY position
M101            ----- Perform exploration
G91G01Z-100F100 ----- Search distance and speed
M102            ----- End exploration action
G04P0;          ----- pause 0s
# 402 = # 400;   ----- G53 Coordinate system Z Zero offset average
# 403 = 1;      ----- Enable automatic correction of the coordinate system flag
# 404 = - # 870; ----- Record the Z G53 position of the initial tool setting
G91G01Z # 575F # 578; ----- The tool setting is completed and the Z axis is retracted
```